

**TOYOTA KLUGER
GSU50/55
Vacuum Pump Safety Related Recall Campaign**

Involved Vehicle VIN details

5TDBZ3FH50S492812
5TDBZ3FH60S492835
5TDBZ3FH30S492906
5TDBZ3FH40S493014
5TDBZ3FH80S493050
5TDBZ3FH80S493145
5TDDZ3FH40S492731
5TDDZ3FH90S492871
5TDYZ3FH20S237772
5TDZZ3FH60S237729
5TDZZ3FH80S237733
5TDZZ3FH90S237742
5TDZZ3FH00S237760
5TDZZ3FH60S237780
5TDZZ3FH50S237785
5TDZZ3FH00S237807
5TDZZ3FH20S237811
5TDZZ3FH30S237820
5TDZZ3FH70S237870
5TDZZ3FH40S237874
5TDZZ3FH20S237887